



CIVIL AVIATION AUTHORITY

Aviation Safety Regulation Directorate
Flying Operations Branch

P. O. BOX 684, BOROKO NCD, Papua New
Guinea

Tel: (675) 3244501 / Fax: (675) 3244485

Email: flyingops@datec.net.pg

**NOTICE TO ALL OPERATORS WITH TURBINE POWERED
AEROPLANES, CERTIFICATED FOR MORE THAN 30 PASSENGER
SEATS.**

SUBJECT: Terrain Awareness Warning System (TAWS) and Airborne Collision Avoidance System (ACAS II) implementation.

In accordance with CARs 121.379 & 121.381 all Certificate Holders are reminded to ensure that each Turbine Powered Aeroplane it operates which is certificated for more than 30 passenger seats is equipped with TAWS and ACAS II after 01 July 2005. See copy of applicable CARs below.

121.377 Ground proximity warning system

Except as provided for in 121.379(b) a certificate holder shall ensure that each of its turbine powered aeroplanes is equipped with a GPWS.

121.379 Terrain awareness warning system (TAWS)

(a) After 1 July 2005, a certificate holder must ensure that each turbine-powered aeroplane it operates which is certificated for more than 30 passenger seats is equipped with TAWS.

(b) Notwithstanding the date specified, a certificate holder who complies with paragraph (a) does not need to comply with 121.377.

121.381 Airborne collision avoidance system (ACAS)

After 1 July 2005, a certificate holder shall ensure that each turbine-powered aeroplane it operates which is certificated for more than 30 passenger seats is equipped with ACAS II.

Wilson Sagati
Deputy Director, Aviation Safety Regulation